


(E5.4) A feedback system with negative unity feedback has a loop transfer function

$$L(s) = G_c(s)G(s) = \frac{2(s+8)}{s(s+4)}$$

- Determine the closed-loop transfer function  $T(s) = Y(s)/R(s)$ .
- Find the time response,  $y(t)$ , for a step input  $r(t) = A$  for  $t > 0$ .
- Using Figure 5.13(a), determine the overshoot of the response.
- Using the final-value theorem, determine the steady-state value of  $y(t)$ .



**FIGURE 5.13** (a) Percent overshoot as a function of  $\zeta$  and  $\omega_n$  when a second-order transfer function contains a zero. Redrawn with permission from R. N. Clark, *Introduction to Automatic Control Systems* (New York: Wiley, 1962). (b) The response for the second-order transfer function with a zero for four values of the ratio  $a/\zeta\omega_n$ :  $A = 5$ ,  $B = 2$ ,  $C = 1$ , and  $D = 0.5$  when  $\zeta = 0.45$ .

Ans.

$$(a) T(s) = \frac{L(s)}{1+L(s)} = \frac{2(s+8)}{s^2+6s+16}$$

$$(b) \frac{s-a}{(s-a)^2+b^2} \leftrightarrow e^{at} \cos(bt), \quad \frac{b}{(s-a)^2+b^2} \leftrightarrow e^{at} \sin(bt)$$

$$\text{Step input } R(s) = \frac{A}{s}, \quad Y(s) = \frac{2(s+8)}{s^2+6s+16} \frac{A}{s} = A \left( \frac{1}{s} - \frac{s+4}{s^2+6s+16} \right)$$

$$\begin{aligned} \Rightarrow y(t) &= A \left[ 1 - \left( e^{-3t} \cos \sqrt{7}t + \frac{1}{\sqrt{7}} e^{-3t} \sin \sqrt{7}t \right) \right] \\ &= A \left[ 1 - 1.07e^{-3t} \sin(\sqrt{7}t + 1.21) \right] \end{aligned}$$

$$(c) T(s) = \frac{2(s+8)}{s^2+6s+16} = \frac{\dots}{s^2+2\zeta\omega_n s + \omega_n^2} \rightarrow \zeta = 0.75 \text{ and } \omega_n = 4.$$

$$\text{P.O.} = 100e^{-\zeta\pi/\sqrt{1-\zeta^2}} = 2.83\%$$


(d) This is a type 1 system, thus the steady-state error is zero and  $y(t) \rightarrow A$  as  $t \rightarrow \infty$ .

$$e_{ss} = \lim_{s \rightarrow 0} s[R(s) - Y(s)] = \lim_{s \rightarrow 0} A \left[ 1 - \frac{2(s+8)}{s^2+6s+16} \right] = 0$$

(E5.6) Consider the block diagram shown in Figure E5.6.

- (a) Calculate the steady-state error for a ramp input.
- (b) Select a value of K that will result in zero overshoot to a step input. Provide the most rapid response that is attainable.

Plot the poles and zeros of this system and discuss the dominance of the complex poles. What overshoot for a step input do you expect?



**FIGURE E5.6** Block diagram with position and velocity feedback.

Ans.

(a) Ramp input  $R(s) = \frac{A}{s^2}$ ,  $T(s) = \frac{Y(s)}{R(s)} = \frac{G(s)}{1+G(s)H(s)} = \frac{100}{s^2+100Ks+100}$ , where

$G(s) = \frac{100}{s^2}$  and  $H(s) = 1 + sK$

- The steady-state error is

$$e_{SS} = \lim_{s \rightarrow 0} s[R(s) - Y(s)] = \lim_{s \rightarrow 0} s \left[ \frac{A}{s^2} - T(s) \frac{A}{s^2} \right] = \lim_{s \rightarrow 0} \frac{A}{s} \left[ \frac{s^2+100Ks}{s^2+100Ks+100} \right] = KA$$

(b) Natural frequency  $\omega_n = 10$ , damping ratio  $\zeta = 5K$

ps. **Overdamped**  $\zeta > 1$ , **Underdamped**  $\zeta < 1$ , **critically damping**  $\zeta = 1$   
critically damping  $\zeta = 1 = 5K \rightarrow K = 0.2$


$\Rightarrow$  P. O. =  $100e^{-5K\pi/\sqrt{1-(5K)^2}}$  for  $0 < K < 0.2$

P. O. = 0 for  $K > 0.2$

(E5.17)(a) A closed-loop control system transfer function T(s) has two dominant complex conjugate poles. Sketch the region in the left-hand s-plane where the complex poles should be located to meet the given specifications.

$0.6 \leq \zeta \leq 0.8, \omega_n \leq 10$ .

Ans.  $s_{1,2} = -\zeta\omega_n \pm j\omega_n\sqrt{1-\zeta^2}$




(a)  $0.6 < \zeta < 0.8$  and  $\omega_n < 10$

(E5.17)(d) A closed-loop control system transfer function  $T(s)$  has two dominant complex conjugate poles. Sketch the region in the left-hand  $s$ -plane where the complex poles should be located to meet the given specifications.

$$\zeta \leq 0.707, 5 \leq \omega_n \leq 10.$$

$$\text{Ans. } s_{1,2} = -\zeta\omega_n \pm j\omega_n\sqrt{1-\zeta^2}$$



(d)  $0.707 > \zeta$  and  $5 < \omega_n < 10$

(E5.20) Consider the closed-loop system in Figure E5.19, where  $G_C(s)G(s) = \frac{s+1}{s^2+0.3s}$ ,

and  $H(s) = K_a$ .

- Determine the closed-loop transfer function  $T(s) = Y(s)/R(s)$ .
- Determine the steady-state error of the closed-loop system response to a unit ramp input,  $R(s) = 1/s^2$ .
- Select a value for  $K_a$  so that the steady-state error of the system response to a unit step input,  $R(s) = 1/s$ , is zero.

Ans.

$$(a) T(s) = \frac{Y(s)}{R(s)} = \frac{G_C(s)G(s)}{1+G_C(s)G(s)H(s)} = \frac{s+1}{s^2+0.3s+K_a s+K_a}$$

$$(b) e_{SS} = \lim_{s \rightarrow 0} s[R(s) - Y(s)] = \lim_{s \rightarrow 0} \frac{1}{s} \left[ 1 - \frac{s+1}{s^2+0.3s+K_a s+K_a} \right] = \infty$$

$$(c) e_{SS} = \lim_{s \rightarrow 0} s[R(s) - Y(s)] = \lim_{s \rightarrow 0} \left[ 1 - \frac{s+1}{s^2+0.3s+K_a s+K_a} \right] = K_a - 1$$

$$\Rightarrow e_{SS} = 0 \text{ for } K_a = 1$$

(P5.20) A system is shown in Figure P5.20.

(a) Determine the steady-state error for a unit step input in terms of  $K$  and  $K_1$ , where  $E(s) = R(s) - Y(s)$ .

(b) Select  $K_1$  so that the steady-state error is zero.




FIGURE P5.20 System with pregain,  $K_1$ .

Ans.

$$(a) T(s) = \frac{Y(s)}{R(s)} = \frac{G(s)K_1}{G(s)+1}, G(s) = \frac{K}{(s+5)(s+11)}, R(s) = \frac{1}{s}$$

$$e_{SS} = \lim_{s \rightarrow 0} s[R(s) - Y(s)] = \lim_{s \rightarrow 0} \left[ 1 - \frac{KK_1}{s^2+16s+55+K} \right] = \frac{55+K-KK_1}{K+55}$$

(b) To achieve zero steady-state error,  $K_1 = K + \frac{55}{K}$

\*\*\*\*\* Important Equation in Chapter 5 \*\*\*\*\*

### 1. Second Order System

I. P. O. =  $100e^{-\zeta\pi/\sqrt{1-\zeta^2}}$

II. Overshoot =  $M_{pt} - 1 = e^{-\zeta\pi/\sqrt{1-\zeta^2}}$

III. Peak time  $T_p = \frac{\pi}{\omega_n\sqrt{1-\zeta^2}}$

IV. Settling time  $T_s = 4\tau = \frac{4}{\zeta\omega_n}$

V. Poles  $s_{1,2} = -\zeta\omega_n \pm j\omega_n\sqrt{1-\zeta^2}$

### 2. Standard Test Input Signals

I. Step Signals:  $\frac{A}{s}$

II. Ramp Signals:  $\frac{A}{s^2}$

III. Parabolic Signals:  $\frac{2A}{s^3}$